

● PRINTER RUSH ●
(PTO ASSISTANCE)

Application:	Examiner:	GAU:
10/795865	Gushi	2833
From:	Location:	Date:
PAF	(DC) FMF FDC	12/16/04
Tracking #:		Week Date:
06038686		11/8/04

DOC CODE	DOC DATE	MISCELLANEOUS
<input type="checkbox"/> 1449		<input type="checkbox"/> Continuing Data
<input type="checkbox"/> IDS		<input type="checkbox"/> Foreign Priority
<input checked="" type="checkbox"/> CLM	3/09/2004	<input type="checkbox"/> Document Legibility
<input type="checkbox"/> IIFW		<input type="checkbox"/> Fees
<input type="checkbox"/> SRFW		<input type="checkbox"/> Other
<input type="checkbox"/> DRW		
<input type="checkbox"/> OATH		
<input type="checkbox"/> 312		
<input type="checkbox"/> SPEC		

[RUSH] MESSAGE: Original claim 5 is incomplete. It ends with a semicolon and appears to have missing data.

thank you

[XRUSH] RESPONSE:

In the claim,

Claim 5, line 2, "sea" has been changed into -- seat --

Claim 5, last line, ";" has been changed into -- o --

INITIALS: CB

NOTE: This form will be included as part of the official USPTO record, with the Response document coded as XRUSH.

REV 10/04

wireless transmission device is installed in the interface cartridge for storing received data in the memory card.

5. The multiple-in-one retaining seat as claimed in claim 1, wherein the embedding groove at an upper end of the backside of the retaining seat is protruded with the mask for receiving the speaker; the speaker is electrically connected to the circuit board for providing a hand free function/.